

# Blast HD™

## Industrial Strength Problem Solver



### DESCRIPTION & USE

**Blast HD™** is a fast acting industrial strength problem solver formulated to help remove smoke, soot, hydrocarbons, rust, bore water stains, mineral deposits & red soil marks. It is also effective in removing the most extreme type of built up grime and dirt where other cleaning products have not been as effective. Can also be used to etch concrete. **USE:** On all ACID RESISTANT natural stone, ceramic tiles, porcelain, terracotta & masonry surfaces.

### TEST FIRST

Due to the nature of different surfaces, you should do several test areas in inconspicuous areas according to the label instructions to determine surface colour stability and desired results. The end user must determine the suitability of the product for their intended use.

### PRECAUTIONS & SAFETY DIRECTIONS

1. Read entire label, SDS & technical bulletin before using;
2. Wear appropriate skin & eye protection & use in a well ventilated area;
3. Surface must be clean, dry & free from any sealers & coatings;
4. Use when surface temperature is between 4°C & 32°C;
5. Do **NOT** mix with other chemicals or allow contact with any non-recommended surfaces;
6. Do **NOT** use on acid sensitive or polished surfaces;
7. Do **NOT** mix in metal containers;
8. Remove all metal jewellery before using;

### INSTRUCTIONS

1. Sweep, vacuum, or wipe surface;
2. If the surface is very porous, slightly pre-wet surface with water;
3. Dilute **Blast HD™** as follows:
  - a) LIGHT: Mix 1 part product to 8 parts water;
  - b) MODERATE: Mix 1 part product to 5 parts water;
  - c) HEAVY: Mix 1 part product to 3 parts water;
  - d) EXTREME: Mix 1 part product to 1 part water or use neat;
4. Carefully apply solution to surface with a sponge, roller or mop;
5. Allow minimum dwell time of 10 minutes - up to 30 minutes
6. **DO NOT ALLOW THE PRODUCT TO DRY ON THE SURFACE;**
7. Scrub with a white nylon pad, scrub brush or scrub machine;
8. Remove the dirty solution with a wet vac or mop;
9. Rinse thoroughly with clean water;
10. Repeat the process as necessary.

### LIMITATIONS

- ▶ Heavily soiled surfaces may require longer dwell time and or stronger solution;
- ▶ Some stained surfaces may require resurfacing or replacing

### COVERAGE

The coverage will vary depending on density, porosity, texture, surface absorption, weather conditions, time solution left on surface, the application method, number of applications, severity of the problem and dilution used.

### HANDLING, STORAGE & CLEAN UP

- ▶ Close container tightly after each use
- ▶ Store between 4°C and 32°C.
- ▶ Do not re-use container. Discard in rubbish
- ▶ Clean tools with water.

### FIRST AID

For advice, contact Poisons Information Centre (Aust 131 126, NZ 0800 764766) or a doctor. Ingestion: Do NOT induce vomiting. Give water or milk to drink. Eyes: Immediately flush eyes with clean, running water for at least 15 minutes, & see a doctor. Skin & Hair: Remove contaminated clothing. Immediately wash contaminated skin & hair with plenty of water. Inhalation: Remove victim from exposure, to fresh air. Seek medical advice. General: If irritation persists or feeling unwell, seek medical attention.

Code	Size	Barcode Number
123-005	1 litre - Blast HD	9347177001326
123-006	4 litre - Blast HD	9347177001333

### PRODUCT WARRANTY

Aqua-Seal STS™ "The Manufacturer" warrants to the original purchaser of its products that such products are free from manufacturing defect and does not warrant or guarantee the workmanship performed by any person or firm installing its products. The manufacturer's obligation under this warranty is limited solely to the original purchaser and solely shall be limited to the replacement of the product sold or refund. This warranty will not extend to any product which has been modified in any way or which has not been used in accordance with the printed instructions. The manufacturer makes no other warranties either expressed or implied. The end user must determine the suitability of the product for their intended use. **READ ENTIRE LABEL & ALWAYS DO A TEST FIRST.**